

RADIOLOGICAL SAFETY HEADQUARTERS at

899-(2)/TJB:fpw
Serial: 0256

CONFIDENTIAL

CONFIDENTIAL

13 January 1947

From: RadSafe Headquarters, San Francisco, California.
To : Bureau of Ships Code 180-A.
Subject: Graving Docks and Floating Dry Docks, Radiological Monitoring of.
Reference: (a) BUSHIPS Conf. ltr C-S(99)-(2)-(2)(180-A) over C-EN28/A2-11 of 23 December 1946.

1. Drydocks Nos. 3, 4 and 6 at the San Francisco Naval Shipyard were monitored in accordance with reference (a) with the following results:

- (a) Drydock No. 3 - all background.
- (b) Drydock No. 6 - all background.
- (c) Drydock No. 4 -
 - (1) Waterway, Station 790, northeast side - .007 gb.
 - (2) Waterway, Station 765, northeast side - .005 gb.
 - (3) Remainder of drydock - background.

2. The readings obtained in Drydock No. 4 were taken on sand accumulations in the waterways.

3. No other Drydocks were used to dock ex-CROSSEADS vessels.

T. J. BRATTEN, Jr.

cc: BUREAU
BUOYSDOCKS
CCM SPNS

599(2)
1-13-47